

2-1/2-story commercial building, Morristown, New Jersey

Problem: Front masonry wall leaning 5 inches toward the street.
Solution: Designed and built interior steel frame to restore wall to its original position.

