

2-story residence, Riverdale, New Jersey

Problem: First and second floors partially failed and deflected up to 4 inches.

Solution: Design and installed reinforcement of all girders and joists, avoiding probable demolition. Restored floors to near-original levels.

