



2-story residence, Denville, New Jersey
Problem: First and second levels exhibiting major deflections due to under designed joists and girders.
Solution: Designed and installed and reinforcement for numerous components to stabilize and level floors.