



3-story landmark barn converted to office and retail space

Problem: Truss system supporting roof and top level failed.

Solution: Designed and installed steel cable tie system to relieve thrust from exterior walls.