



3-story brownstone residence, Jersey City, New Jersey

Problem: Sagging floors and vibration from traffic.
 Solution: Designed and installed girder and header reinforcement to stabilize and level floors.